



www.labjack.com

 STATUS

U12

Screw Terminals 1-15	1	AI0	IO0	16
		AI1	IO1	
		GND	GND	
		AI2	IO2	
		AI3	IO3	
		GND	GND	
		AI4	AO0	
		AI5	AO1	
		GND	GND	
		AI6	CNT	
		AI7	GND	
		GND	GND	
		+5V	+5V	
		+5V	+5V	
	15	CAL	STB	30
Screw Terminals 16-30				